

Consolidated Report of Inspections conducted from August to September 2025

Details on the CETPs

Sl. No.	Name and Address of CETP / IETP	Consented capacity (KLD)	Whether the quantity is in excess of the consented quantity	Whether treatment system provided (Primary, Secondary treatment then RO, MEE, ATFD)	Deficiencies noted in the treatment system	Any unauthorised disposal found. If any	Status of storage of mixed salt & discrepancy if any	Whether the hazardous waste display board has been updated	Whether hazardous waste is stored & disposed as per hazardous waste Rules	Status of OCEMS connectivity	In case of violation mentioned in the preceding columns, then the status of action taken
1	2	3	4	5	6	7	8	9	10	11	12
01	M/s. Ambur Tannery Effluent Treatment Co. Lt. (Maligai Thope Sector), S.F.No. 2/1, 2/2, 2/3, 3/1, 3/2 part, Ambur village, Ambur Taluk, Tirupathur District	1100	No	Yes	---	No	Stored at Closed Roof Shed	Yes	Yes	7 nos. EMFMs are connected to WQW Centre, TNPCB.	ZLD system is in operation.
02	M/s. Ambur Tannery Effluent Treatment Company Ltd., Thuthipet Sector, S.F.No. 114/1, 2, 3, 115, 134/1, 3, 147/2, 3, 4, 110/3, 111/2, 117, 133/1, 135/2, 136/1, 142/2, 132/3, 118, 119, 101/2A,	2219	No	Yes	RO membranes in RO to be replaced / revamped.	No	Stored at Closed Roof Shed	Yes	Yes	14 nos. of EMFMs are connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.

	Periyavarikkam Village, Ambur Taluk, Tirupathur District										
03	M/s TALCO Pernambut Tannery Effluent Treatment Company Limited, S.F.No. 177, 174/1, 174/3, 184, 188/2, 167/1A, 167/1B, 171/1A, 171/1B, 171/2, 188/1, 194/1C, 173, 186, 175, 182/2A, 182/2B, Chinnathamalsiruvu Village, Pernambut Taluk, Vellore District	891	No	Yes	DO meter at the outlet of Aeration tank to be installed.	No	Stored at Closed Roof Shed	Yes	Yes	16 nos. of EMFMs are connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.
04	M/s Vanitec Limited, S.F.No. 43/2, 54/4, 43/4, 55/1A, 55/1B2, etc., Valayampattu Village, Vaniyambadi Taluk, Thiruppathur District	3342	No	Yes	i. A free board of minimum 1 m at the Equalization tank to be maintained. ii. 1 st & 2 nd stage RO system to be revamped and new membranes to be provided. iii. DO meter at the outlet of	No	Stored at Closed Roof Shed	Yes	Yes	24 nos. of EMFM are connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.

					Aeration tank to be installed. iv. Measures to be taken to attenuate odor nuisance at the Equalization tank. v. Good housekeeping to be maintained.						
05	M/s Ranipet SIDCO Finished Leathers Effluent Treatment Company (P) Ltd., Plot No. 191, 197, 198, 199, 200, SIDCO Industrial Estate, Ranipet, Karai Village, Walajah Taluk, Ranipet District	2500	No	Yes	i. A free board of minimum 1m at the Equalization tank to be maintained. ii. RO system to be revamped and new membranes to be provided. iii. DO meter to be installed. iv. RO Reject additionally stored in the tank at the backside of CETP along with rain water to be treated. v. Good housekeeping to be maintained.	No	Stored at Closed Roof Shed	Yes	Yes	26 nos. of EMFMs are connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.

06	M/s SIPCOT - SIDCO Phase-II Entrepreneur Finished Leather Effluent Treatment Co. (P) Ltd., S.F.No. 239/1, Narasingapuram Village, Walajah Taluk, Ranipet District	1560	No	Yes	i. A free board of minimum of 1 m at the Equalization tank to be maintained. ii. RO system to be revamped and new membranes to be provided. iii. PTZ camera to be maintained in proper working conditions. iv. Log books to be maintained.	No	Stored at Closed Roof Shed	Yes	Yes	17 nos. of EMFMs are connected to WQW Centre, TNPCB.	Directions vide proceeding dated 08.09.2025 were already issued to the CETP for compliance. The member units of the CETP were also directed to stop their operation until the CETP complies with the directions.
07	M/s Ranipet Tannery Effluent Treatment Company, S.F.No. 636/8, 617/2, 617/3, 618/1, 618/2, 634/2, 636/6, 597/1, 2, 601, 602, 603, 605, 603/3, 606, 607, 608/1, 3, 4, 613/1, 2, 3, 5, 612/1, 2, 3A etc., Vannivedu Village, Walajah Taluk, Ranipet District	4500	No	Yes	i. Scum formation from the Equalization tank to be removed. ii. Good housekeeping to be maintained.	No	Stored at Closed Roof Shed	Yes	Yes	33 nos. of EMFMs are connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.

08	M/s Visharam Tannery Enviro Control Systems Private Limited, S.F.No. 305/8B, 306, 305/1D, 305/2, 307/4, Visharam Village, Walajah Taluk, Ranipet District	3400	No	Yes	i. A free board of minimum of 1 m at the Equalization tank to be maintained. ii. RO system to be revamped and new membranes to be provided. iii. Log books to be maintained. iv. ETP components, staircase & ladder in the Old MEE system to be revamped. v. PTZ camera to be maintained in proper working condition.	No	Stored at Closed Roof Shed	Yes	Yes	12 nos. of EMFMs are connected to WQW Centre, TNPCB.	Directions vide proceeding dated 03.09.2025 were already issued to the CETP for compliance. The member units of the CETP were also directed to stop their operation until the CETP complies with the directions.
----	---	------	----	-----	---	----	----------------------------	-----	-----	--	---

Details on the members units attached to the CETP

Team	Number of member units	Number of member units under operation	Whether effluent conveyed to the CETP (Yes / No)	Any unauthorised disposal found if any	In case of violation mentioned in the preceding columns, then status of action taken.
Team 2	48	43	Yes	0	-
Team 3	55	43	Yes	3	Closure Direction issued to the 3 member units
Team 4	74	20	Yes	4	Closure Direction under issue
Team 5	74	67	Yes	0	-
Team 6	48	40	Yes	0	-
Team 7	55	47	Yes	0	-
Team 8	48	38	Yes	0	-
Team 9	55	41	Yes	0	-
Total	457	339	-	7	-

* Apart from the above mentioned 7 member units, direction for closure and disconnection of power supply has been issued to 2 member units (viz. M/s. C. Nayeem Leather Corporation and M/s. Amra International) based on regular inspection.

Details on the IETPs

Sl. No	Name and Address of IETP	Consented Capacity (KLD)	Whether the quantity is in excess of consented quantity	Whether treatment system provided (Primary, Secondary treatment, then RO, MEE, ATFD)	Deficiencies noted in the treatment system	Any unauthorised disposal found if any	Status of storage of mixed salt & discrepancy if any	Whether hazardous waste display board updated	Whether hazardous waste stored & disposed as per Hazardous Waste Rules	Status of OCEMS connectivity	In case of violation mentioned in the preceding columns then status of action taken
01	M/s.Swamiand Company, S.F.No.27/1, Valayampattu village, Vaniyambadi Taluk, Tirupathur District	60 KLD	The unit was not under operation, since Direction for Closure issued by Board								
02	M/s. FARIDA PRIME TANNERY PVT LTD, A-UNIT, S.F.No. 318/1, 320/2, THUTHIPATTU village, Ambur Taluk, Tirupathur District	240	No	Yes	No	No	Salt stored in closed shed within the premises.	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
03	M/s. FLORENCE SHOE COMPANY PVT LTD	56	No	Yes	No	No	Salt stored in closed shed	Yes	Yes	Connected	---

	(LEATHER DIVISION-TANNERY) , S.F.No. 17/1, Ambur Village, Ambur Taluk, Tirupathur District						within the premises.				
04	M/s. N.M.ZACKRIAH & CO., S.F.No. 68,69, & 71, PERIAVARIKKAM village, Ambur Taluk, Tirupathur District	165	No	Yes	No	No	Salt stored in closed shed within the premises.	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
05	M/s TATA INTERNATIONAL LIMITED, (BACHI SHOES DIVISION- UNIT-LEATHER DIVISION) S.F.No.163/1,163/2,164/1, 164/2, 165/1, 165/2,166,167/1,167/2A,167/2 B & 168/3B, PERIAVARIKKAM,village, Ambur Taluk, Tirupathur District	105	No	Yes	No	No	Salt stored in closed shed within the premises.	Yes	Yes	Connected	---
06	M/s Hindustan Leathers, S.F.No.9/5 Part,	23.5	The unit was not in operation and was closed by the unit itself								

	Perumalpet, Vaniyambadi Taluk, Tirupathur District										
07	M/s. HABEEB TANNING COMPANY-TANNERY DIVISION, S.F.No. 18/1, 19/1, 20, 21, 103, 104/2A, 104/3, 105 & 108, Arimmanankuppam village, Gudiyatham Taluk, Vellore District	100.5	The quantity is within the consented quantity	Yes	No	No	Salt stored in closed shed within the premises.	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
08	M/s.TM ABDUL RAHMAN & SONS, B UNIT (IETP), S. F. No.2/1, 2A, 2C, 3, 4, 5/1, 6, 7, 8, Manthangal Village, Walajah Taluk, Ranipet District	174	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
09	M/s. ATH LEDER FABRIK, S. F. No. 348/3, 348/4(p), 349/1A, 349/1B, 349/1C, 349/1D, 349/1E, 349/1F, 349/2, 349/3, 349/4, 350/1 & 350/2, Visharam Village, Walajah Taluk, Ranipet District.	322.5	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	Connected	--
10	M/s. K H Exports India Private Limited, Tannery 'A' Division, S.F. No. T.S.NO. Part	830	No	Yes	No	No	Salt stored in closed shed	Yes	Yes	Connected	--

	5/2,5/2B,3A,3B,4/1,2, Block NO.18,3,1/1,5B,5A,6/1,3/1A,2/1, Block No.20, Walajah Village, Walajah Taluk, Ranipet District.						within the premises				
11	M/s. P A Footwear (P) Ltd Unit-II, S.F.No.51-C, Narasingapuram Village, Walajah Taluk and Ranipet District.	25	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
12	M/s Golden Leathers, R.S. No118,119-2,117-1B, Adiyur Village,, Tirupattur Taluk, Tirupathur District - 635 655	53 KLD	No	Primary, Secondary and RO system provided followed by Solar Evaporation Pan	SEP is not adequate	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity and ensure that there is no overflow from the SEP.

13	M/s. Aafaq Leathers, S.F. No. 10/7, 11/3, 11/4, 10/6, Valayampattu Village, Vaniyambadi Taluk,, Tirupathur District	33 KLD	No	Primary, Secondary and RO system provided followed by Solar Evaporatio n Pan	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
14	M/s. Smita Exports Private Limited., S.F No. 157, Mittalam Village, Ambur Taluk, Tirupathur District	72 KLD	No	Primary, Secondary and RO system provided followed by Solar Evaporatio n Pan	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
15	M/s SRI VINAYAGA TANNERS, S.F.No. 204/1A, Periyavarikkam Village, Ambur Taluk, Tirupathur District	50 KLD	No	Primary, Secondary and RO system provided followed by Solar Evaporatio n Pan	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
16	M/s. SHAFEEQ SHAMEEL & CO. A UNIT	195	No	Yes	No	No	Salt stored in closed	Yes	Yes	The unit is yet to	ZLD system is in

	S.F No. 3 & 6, Venkatasamudram Village, Ambur Taluk, Tirupathur District.						shed within the premises			provide OCEMS.	operation. The unit has been instructed to establish OCEMS connectivity
17	M/s. Shalimar Tanning Company., S.F. No. 75/2F2 Part & 11/1A, Solur Village, Ambur Taluk, Tirupathur District.	66	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish OCEMS connectivity
18	M/s. T. Abdul Wahid Tanneries Pvt Ltd -C Tannery, S.F No. 197/1,197/3, Solur Village, Ambur Taluk, Tirupathur District.	50	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	Connected	—
19	M/s. Hiba Tanning Company- Tannery Division S.F No. 122/3A3 Part Chinnavarigam Village, Ambur Taluk, Tirupathur District - 635 802	21.5 KLD	No	Primary, Secondary and RO system provided followed by Solar	No	No	Salt stored in closed shed within the premises	Yes	Yes	The unit is yet to provide OCEMS.	ZLD system is in operation. The unit has been instructed to establish

				Evaporati on Pan							OCEMS connectivity
20	M/s. K.MD.Mohibullah and Co, S.F.No. 28 Part, 29 Part, Thuthipattu Village , AmburTaluk, Tirupathur District.	20	Self closed – not in operation for the past 5 years.								
21	M/s. T. ABDUL WAHID TANNERIES PVT LTD -B TANNERY S.F No. 193,194,196,206/1,188,190/2,1 91/1B, Solur Village, AmburTaluk, Tirupathur District.	125	No	Yes	No	No	Salt stored in closed shed within the premises	Yes	Yes	Connected	---