



## **TAMILNADU POLLUTION CONTROL BOARD**

## Proceeding No. T2/TNPCB/F.8636TLR/W&A/2019-1, dated: 08.08.2019

Sub: TNPCB – Industries – M/s. Shree Balaji Chem Industries, Plot, No. 94, 95
SIDCO Industrial Estate, S.F.No. 274, Kakkalur Village, Tiruvallur Taluk,
Tiruvallur District - Violations under Water (P&CP) 1974 as amended and Air
(P&CP) as amended - Closure directions under Section 33A of the Water
(P&CP) Act, 1974 as amended and under Section 31A of the Air (P&CP) Act
1981 as amended – Orders issued – reg.

Ref:

- 1. Proceedings No.F. 0540TLR/RS/DEE/TNPCB/TLE/W&A/2017 Dt. 4.10.2017
- 2. Proc.No. .F.-TLR0160/W&A/2019 Dr. 29.3.2019.
- 3. Unit's reply letter dated:0.3.05.2019.
- IR .No.: R.TLR0160/RS/DEE/TLR/2019 Dt.29.6.2019, enclosed vide DEE Lr.
   No. R.TLR0160/DEE/TKLR/2019 Dt. 29.6.2019.

\*\*\*\*\*\*

Whereas the unit of M/s. Shree Balaji Chem Industries, Plot, No. 94, 95 SIDCO Industrial Estate, S.F.No. 274, Kakkalur Village, Tiruvallur Taluk, Tiruvallur District was issued with consent of the Board under the Water (P&CP) Act, 1974 as amended and Air (P&CP) Act, 1981 as amended and renewed the same with validity upto 31.03.2020 vide reference first cited

Whereas show cause notice was issued to the unit vide reference 2<sup>nd</sup> cited for the non-compliance of the condition imposed in the consent order & subsequently the unit vide reference 3<sup>rd</sup> cited has furnished reply for the show cause notice issued and the reply furnished by the unit is not satisfactory.

Whereas, the unit was again inspected by the District Environmental Engineer on 28/06/2019 and the following were noticed.

- 1) At the time of inspection the unit was not in operation and it was reported that the unit was carrying out the activity intermittently.
- 2) The Spent Solvent as received through tankers is transferred into Plastic container/barrels stored on the open land without providing impervious platform and in the sheds for the storage of raw materials received.
- Spillage of solvent was found deposited on open land and the same was washed away during rainy season.
- 4) The raw material storage tank is found in damaged condition and no venting is provided in the storage tank and no condenser provision is made for recovery of VOC during unloading operation.

- 5) The distillation unit is kept outside the shed on Earthen ground without any flooring arrangement.
- 6) The unit has not provided any arrangements for the adsorption of VOC from the distillation column.
- 7) There is no laboratory facility within the premises.
- 8) The unit has not provided any earmarked area for the storage Raw material, Product, Spent Residue etc. Barrels containing the raw material, finished product, distillation residue waste etc. were being stored in barrel within the premises in a haphazard manner and without any labelling.
- 9) The unit was not maintaining any records for the disposal of the distillation residue generated from the solvent. Distillation operations.
- 10)Residue generated from the distillation unit is collected in open barrel and kept on the open land without any cover and spillages on the open land from the barrel was also noticed. The unit has not provided impervious platform and sheds for its storage.
- 11)All the discarded / used drums are kept in an open yard and the same is not disposed properly as per the provision of Hazardous and Other Wastes (M&TB) Rules 2016.
- 12) The unit has not maintained log book with information on source and date of procurement of Spent Solvent, quantity, percentage content of solvent and moisture in the same, date wise utilization of the same, hazardous waste generation and its disposal etc.
- 13) The unit has not maintained record of hazardous waste utilized, hazardous waste generated and disposed as per Form 3 and has not submitted returns in Form 4 as per the Rule 20 (1) and (2) of the Hazardous and Other Wastes (M&TB) Rules 2016 to TNPCB.

In view of the above, the DEE has recommended for issue of direction for Closure and disconnection of power supply to the unit may be considered under Section 33A of Water (P&CP) Act 1974 as amended and under section 31A of the Air (P&CP) Act 1981 as amended.

In light of the above facts and in exercise of the powers conferred under section 33A of the Water (Prevention and Control of Pollution) Act 1974 as amended and under section 31A of the Air (P&CP) Act 1981 as amended, it is decided to issue directions for closure and for stoppage of electricity to the unit M/s. Shree Balaji Chem Industries, Plot, No. 94, 95 SIDCO Industrial Estate, S.F.No. 274, Kakkalur Village, Tiruvallur Taluk, Tiruvallur District

Now, therefore, as per the above decision, it is hereby directed under section 33A of the Water (Prevention and Control of Pollution) Act 1974 as amended and under section 31A of the Air (P&CP) Act 1981 as amended that the unit of M/s. Shree Balaji Chem Industries, Plot, No. 94, 95 SIDCO Industrial Estate, S.F.No. 274, Kakkalur Village, Tiruvallur Taluk, Tiruvallur District shall be disconnected with power supply and closed with immediate effect.

This order of closure and disconnection of power supply is issued by the Chairman as per the delegation of powers issued by the Board vide BP.Ms.No.9 dated 11.03.1994.

Chairman(FAC)

To

The Proprietor

M/s. Shree Balaji Chem Industries,

Plot, No. 94, 95 SIDCO Industrial Estate,
Kakkalur Village,
Tiruvallur Taluk,
Tiruvallur District – 602 003.

## Copy to:

1. The Joint Chief Environmental Engineer (Monitoring),
Tamil Nadu Pollution Control Board
2nd Floor, 77-A, South Avenue Road,
Ambattur Industrial Estate,
Chennai – 600038

Phone: 044-26880219

Email: tnpcobmchn@gmail.com

- District Environmental Engineer, Tamil Nadu Pollution Control Board, Plot No. 41, | street, Judges Colony, Tiruvallur -602001 Phone 044 27664425 Email: tnpcb.tlr@gmail.com
- 3. The District Collector, Tiruvallur

- The Superintending Engineer, 4. TANGEDCO (Tamilnadu Electricity Board), Anna Maaligai, Olimohamdpet, Kanchipuram, kancheepuram District - 631 502 E mail- sekcpm@tnebnet.org
- The Assistant Engineer/O&M/TANGEDCO 5. (Tamilnadu Electricity Board), 110 KVA SS Putlur Railway Station Road, Neat Anchanyar Kovil Tiruvallur Taluk, Tiruvallur District – 602 003 E mail- vlk363ae@tnebnet.org
- 6. File Copy