

SLP 23633 – 23634 of 2010 – Inspection of CETPs, IETPs & Member Units

Consolidated Report of inspections conducted between October 2025 to December 2025

(Third Quarter)

Format for CETPs:

Sl. No.	Name & Address of the CETP (as mentioned in the Consent Order)	Consented capacity (KLD)	Whether treatment system provided (Primary, Secondary treatment, then RO, MEE, ATFD)	Whether the quantity is in excess of consented quantity	Deficiencies noted in the treatment system	Any unauthorized disposal found, if any	Status of storage of mixed salt & discrepancy if any	Whether hazardous waste display board updated	Whether hazardous waste stored & disposed as per Hazardous Waste Rules	Status of OCEMS connectivity	In case of violation mentioned in the preceding columns, then status of action taken
1.	M/s. Ambur Tannery Effluent Treatment Company Ltd., Thuthipet Sector, S.F.No.114/1,2,3,115, 134/1,3, etc., Periavarikkam village, Ambur Taluk, Tirupathur District	2219	Yes	No	(i) DO meter (01 No.) to be reinstalled after servicing in the Aeration tank. (ii) Unused Oxidation Ditches, unused anaerobic contact tank and old MEE feed tank to be dismantled.	No	Stored at Closed Roof Shed	Yes	Yes	14 nos of EMFM Connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance.

2.	M/s. Ambur Tannery Effluent Treatment Co. Ltd. (Maligaithope Sector), S.F. No. 2/1, 2/2, 2/3, 3/1,3/2 Part, Ambur village, Ambur Taluk, Tirupathur District	1100	Yes	No	(i) RO membranes to be replaced / revamped (ii) TDS in the MEE Condensate to be reduced.	No	Stored at Closed Roof Shed	Yes	Yes	07 nos of EMFM Connect ed to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance
3.	M/s. SIPCOT & SIDCO Phase II Entrepreneur Finished Leather Effluent Treatment Company (P) Ltd, Plot No105, SIPCOT Industrial Estate, Phase II, Puliyanthangal, Ranipet District	1560	Yes	No	(i) RO membranes to be replaced / revamped	No	Stored at Closed Roof Shed	Yes	Yes	17 nos of EMFM Connect ed to WQW Centre, TNPCB.	Directions vide proceeding dated 12.11.2025 were already issued to the CETP for compliance. The member units of the CETP were also directed to stop their operation until the CETP complies with the directions.
4.	M/s. Visharam Tannery Enviro Control Systems Private Limited., S.F. No. 305/8B, 306, 305/1D, 305/2, 307/4, Visharam	3400	Yes	No	(i) RO system to be revamped (ii) Sludge drying beds and polishing pond to be dismantled (iii) ETP components, staircase & ladder in the Old MEE system to be revamped. (iv) PTZ camera to be maintained in	No	Stored at Closed Roof Shed	Yes	Yes	12 nos of EMFM Connect ed to WQW Centre, TNPCB.	Directions vide proceeding dated 03.09.2025 were already issued to the

	Village, Walajah Taluk, Ranipet District				proper working condition.						CETP for compliance. The member units of the CETP were also directed to stop their operation until the CETP complies with the directions.
5.	M/s. Ranipet Tannery Effluent Treatment Company, S.F. No. 636/8, 617/2, 617/3, 618/1, 618/2, 634/2, 636/6, 597/1&2, 601, 602, 603, 605, 603/3, 606, 607, 608/1,3&4, 613/1,2,3&5, 612/1,2&3A etc., Vannivedu village, Walajah Taluk, Ranipet District	4500	Yes	No	(i) RO membranes to be replaced / revamped in Skid IV. (ii) EMFMs to be installed for backwash water from ETP components	No	Stored at Closed Roof Shed	Yes	Yes	33 nos of EMFM and Stream flow of Boiler, MEE 1&2 along with ATFD Connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance
6.	M/s. Vanitec Private Limited (formerly Vanitec Limited), S.F. No. 43/2, 54/4, 43/4, 55/1A, 55/1B2, 41/1, 56/2, 43/1, 56/2, 54/2B, 41/2, 41/4, etc.,	3342	Yes	No	(i) Free board of minimum 1 meter at the Equalization tank to be maintained. (ii) RO membranes to be replaced / revamped (iii) .DO meter at the inlet and outlet of aeration tank to be installed.	No	Stored at Closed Roof Shed	Yes	Yes	24 nos of EMFM Connected to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been

	Valayampattu village, Vaniyambadi Taluk, Thiruppathur District										communicated for compliance
7.	M/s. Ranipet SIDCO Finished Leathers Effluent Treatment Company (P) Ltd., Plot No. 191, 197, 198, 199, 200, SIDCO Industrial Estate, Ranipet, Karai Village, Walajah Taluk, Ranipet District	2500	Yes	No	(i) Free board of minimum 1 meter at the Equalization tank to be maintained. (iv) .DO meter at the outlet of aeration tank to be installed. (ii) .RO membranes to be replaced / revamped in the 1 st stage (iii) RO Reject additionally stored in the tank at the backside of CETP along with rain water to be treated. (iv) Temporary sludge storage shed to be revamped and possibility of providing new temporary sludge storage to be explored. (v) .Fume generation from HCL storage to be arrested.	No	Stored at Closed Roof Shed	Yes	Yes	26 nos of EMFM Connect ed to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance
8.	M/s. Talco Pernambut Tannery Effluent Treatment Company Limited, S.F. No. 177, 174/1, 174/3, 184, 188/2, 167/1A, 167/1B, 171/1A, 171/1B, 171/2, 188/1,194/1C, 173,186, 175, 182/2A,182/2B, Chinnathamalsiruvu village, Pernambut Taluk, Vellore District	891	Yes	No	(i) DO meter at the outlet of aeration tank to be installed. (ii) Old sludge drying beds, defunct solar evaporation pans, unused equalization tank, old reactivated clarifier and old pelletizers to be dismantled	No	Stored at Closed Roof Shed	Yes	Yes	16 nos of EMFM Connect ed to WQW Centre, TNPCB.	ZLD system is in operation. The observations during inspection have been communicated for compliance

Abstract:

Total number of CETPs allotted for inspection	8
Total number of CETPs inspected	8
Number of CETPs under operation	6
Number of CETPs recommended for Closure & disconnection of power supply	-
Number of CETPs recommended for Directions	-
Number of CETPs recommended for SCN	-
Number of CETPs recommended to address letter	8
No action required	

Details on the member units attached to the CETP

Team	Number of member units	Number of member units under operation	Whether effluent conveyed to the CETPs Yes/No	Any unauthorised disposal found if any	In case of violation mentioned in the preceding columns, then status of action taken.
Team 2	165	131	Yes	3	Directions under issue.
Team 3	148	58	Yes	---	---
Team 4	149	126	Yes	---	---

*Apart from the above-mentioned units, directions for closure and disconnection of power supply were issued to 9 member units (4 member units based on the violations observed by the inspection teams in the previous quarter, 5 member units based on the violations observed during the regular inspection).

Format for IETPs

Sl. No .	Name & Address of the IETP (as mentioned in the Consent Order)	Consent ed Capacity	Whether treatmen t system provided (Primary, Seconda ry treatmen t, then RO, MEE, ATFD)	Whether the quantity is in excess of consent ed quantity	Deficienci es noted in the treatment system	Any unauthoriz ed disposal found, if any	Status of storage of mixed salt & discrepan cy if any	Whether hazardo us waste display board updated	Whether hazardous waste stored & disposed as per Hazardous Waste Rules	Status of OCEMS connect ivity	In case of violation mentioned in the preceding columns, then status of action taken
1.	M/s. HABEEB TANNING COMPANY-TANNERY DIVISION, S.F. No. 18/1, 19/1, 20, 21, 103, 104/2A, 104/3, 105 & 108, Ammanankuppam village, Gudiyatham Taluk, Vellore District	100.4	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
2.	M/s. K H EXPORTS INDIA PRIVATE LIMITED, TANNERY 'A' DIVISION, S.F. No. T.S.NO. Part 5/2, 5/2B, 3A, 3B, 4/1, 2, BLOCK NO. 18, 3, 1/1, 5B, 5A, 6/1, 3/1A, 2/1, BLOCK NO. 20, WALLAJAH village, Walajah Taluk and Ranipet District	830	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	Yes	--
3.	M/s. ATH LEDER FABRIK,	322.5	Yes	No	No	No	The unit	Yes	Yes	Yes	--

	S.F. No. 348/3, 348/4(p), 349/1A, 349/1B, 349/1C, 349/1D, 349/1E, 349/1F, 349/2, 349/3, 349/4, 350/1 & 350/2, VISHARAM village, Walajah Taluk and Ranipet District						has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing				
4.	M/s. P A FOOTWEAR (P) LTD UNIT-II, S.F. No. 51-C, Narasingapuram village, Walajah Taluk and Ranipet District	24.9	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
5.	M/s. T M ABDUL RAHMAN & SONS, B UNIT, S.F. No. 2/1, 2A, 2C, 3, 4, 5/1, 6, 7, 8, MANTHAANGAL village, Walajah Taluk and Ranipet District	174	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	Yes	--
6.	M/s. Farida Prime Tannery Pvt Ltd, A Unit, S.F. No. 318/1, 320/2,	240	Yes	No	No	No	The unit has stored the Salt in	Yes	Yes	Yes	--

	Thuthipattu Village, Ambur Taluk, Tirupathur District						closed shed and has stored sludge in temporary yard and disposed for Co- Processing				
7.	M/s. Florence Shoe Company Pvt Ltd (Leather Division Tannery), S.F.No. 17/1,Ambur Village, Ambur Taluk, Tirupathur District	56	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	Yes	--
8.	M/s. N.M. Zackriah & CO., S.F.No. 68,69, & 71, Periavarikkam village, Ambur Taluk, Tirupathur District	165	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
9.	M/s Tata International Limited, (Bachi Shoes Division Unit-Leather Division) S.F.No.163/1,163/2,164/1, 164/2, 165/1,165/2,166,167/1,167/2A,167/2B	105	Yes	No	No	No	The unit has stored the Salt in closed shed and	Yes	Yes	Yes	--

	& 168/3B, Periavarikkam Village,Ambur Taluk, Tirupathur District						has stored sludge in temporary yard and disposed for Co-Processing				
10	M/s. Shafeeq Shameel &Co. A Unit, S.F. No. 3 & 6, Venkatasamudram Village, Ambur Taluk, Tirupathur District.	195	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
11	M/s. T. Abdul Wahid Tanneries Pvt Ltd -B Tannery, S.F. No.193,194,196,206/1,188,190/2,191/1B, Solur Village, Ambur Taluk, Tirupathur District.	140	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-Processing	Yes	Yes	No	Directions vide proceedings Dated: 29.12.2025 issued to the unit to stop its production until it complies with the directions issued to the unit.
12	M/s. T. Abdul Wahid Tanneries Pvt Ltd -C Tannery, S.F. No. 197/1,197/3, Solur Village,Ambur Taluk, Tirupathur District.	50	Yes The unit is treating the trade effluent	No	No	No	NA	Yes	Yes	Yes	--

			using Combine d RO, MEE and ATFD provided in the sister unit 'M/s. T. Abdul Wahid Tanneries Pvt Ltd -B Tannery								
13	M/s. Shalimar Tanning Company, S.F. No. 75/2F2 Part &11/1A,Solur Village, Ambur Taluk, Tirupathur District.	66	Yes	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
14	M/s. Smita Exports Pvt. Ltd., S.F No. 157,Mittalam Village, Ambur Taluk, Tirupathur District	72	Unit has provided RO followed by SEP only	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co-	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.

							Processing				
15	M/s Sri Vinayaga Tanners, S.F.No. 204/1A, Kailasagiri Road, Periyavarikam Village, Thuthipet, Ambur Taluk, Tirupathur District - 635 811	50	Unit has provided RO followed by SEP only	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
16	M/s Golden Leathers, R.S. No118,119-2,117-1B, Adiyur Village, Tirupattur Taluk, Tirupathur District - 635 655	53	Unit has provided RO followed by SEP only	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
17	M/s. Aafaq Leathers, S.F. No. 10/7, 11/3, 11/4, 10/6,Valayampattu Village, VaniyambadiTaluk,Tirupathur District	33	Unit has provided RO followed by SEP only	No	No	No	The unit has stored the Salt in closed shed and has stored sludge in temporary yard and disposed for Co- Processing	Yes	Yes	No	ZLD system is in operation. The unit has been instructed in this regard.
18	M/s. Hiba Tanning Company- Tannery	21.5	Unit has	No	No	No	The unit has	Yes	Yes	No	Directions

	Division S.F No. 122/3A3 Part Chinnavarigam Village, Ambur Taluk, Tirupathur District - 635 802		provided RO and MEE followed by SEP only				stored the Salt in closed shed and has stored sludge in Temporary yard and disposed for Co- Processing				under issue.
19	M/s. K.MD.Mohibullah & Co. S.F. No. 28 Part, 29 Part, Thuthipattu Village, Ambur Taluk, Tirupathur District.	20	The unit was not in operation and was closed by the unit itself								
20	M/s Hindustan Leathers, S.F.No.9/5 Part, Perumalpet Village, Vaniyambadi Taluk, Tirupathur District	23.5	The unit was not in operation and was closed by the unit itself								
21	M/s. Swami & Co. S. F. No. 27/1, Valayampattu village, Vaniyambadi Taluk, Tirupathur District	60	The unit was not in operation due to closure issued by the Board.								